

SpillTech 5440 McGinnis Village Place Suite 102 Alpharetta, GA 30005 Phone: 1-800-228-3877 Fax: 1-800-872-3764 www.spilltech.com

MATERIAL SAFETY DATA SHEET

SECTION I: IDENTIFICATION OF PRODUCT

PRODUCT NAME:	DrainCovers
CHEMICAL FAMILY:	Polyurethane
MANUFACTURER'S NAME:	PSI Urethanes

Distribution Location:

SpillTech Brookley Industrial Complex 1627 O'Donoghue Street Mobile, AL 36615

Customer Service Telephone Number: 1-800-228-3877 Technical Information Telephone Number: 1-251-694-0102 ext.121

SECTION II: HAZARDOUS INGREDIENTS

INGREDIENTS	PERCENT	CAS NUMBER	<u>OSHA PEL</u>	ACGIH TLV
Polyurethane Elastomer	100%	N/A	N/A	N/A

SECTION III: HAZARDS IDENTIFICATION

NATIONAL FIRE PROTECTION ASSOCIATION (NFPA) RATING:

HEALTH:	0
FLAMMABILITY:	1
REACTIVITY:	0

*Not considered a hazardous material at temperatures below melting point. Not considered a controlled substance or a carcinogen.

SECTION IV: FIRST AID MEASURES

EYE CONTACT:	Use eyewash, consult physician if accompanied by pain or irritation.
SKIN CONTACT:	Wash with soap and water if irritation occurs
INHALATION:	Remove to fresh air if irritation occurs
INGESTION:	induce vomiting as directed by medical personnel

SECTION V: FIRE FIGHTING MEASURES

FLASH POINT: AUTO IGNITION:	N/A N/A
AUTO IGNITION: FLAMMABLE LIMITS: FIRE EXTINGUISHING MEDIA: SPECIAL FIRE FIGHTING PROCEDURES:	N/A N/A Water Spray, Foam, CO2, Dry Chemical Evacuate all non-emergency personnel to a safe location. Use self- contained breathing apparatus. Avoid breathing smoke, fumes or decomposition products. Use water spray to drench smoldering
	elastomer. Product may melt after ignition to form flammable liquids. Burning produces intense heat, dense smoke and toxic gases such as carbon monoxide, oxides of nitrogen and traces of hydrogen cyanide.

SECTION VI: ACCIDENTAL RELEASE MEASURES

If material is released: pick up and handle as any other inert solid material Waste Disposal: Not considered a hazardous waste

SECTION VII: HANDLING AND STORAGE

Always decontaminate after use. When not in use, store with plastic film applied for long life. Keep out of direct sunlight.

Store in dry area. Do not store near open flame, high heat, strong oxidants, or halogenated hydrocarbons. Polyurethane, when heated, becomes very sticky and will burn. Use self-contained air masks to enter smoky area in the event of fire. Adequate ventilation is required to remove decomposition products when temperature exceeds melting point. Avoid contact with melted product.

SECTION VIII: EXPOSURE CONTROLS/ PERSONAL PROTECTION EQUIPMENT

RESPIRATORY PROTECTION: VENTILATION: PROTECTIVE GLOVES: EYE PROTECTION: None Required None Required None Required Safety glasses with side shields are recommended as a good practice for industrial safety. None Required

OTHER PROTECTIVE EQUIPMENT (SPECIFY):

SECTION IX: PHYSICAL DATA

APPEARANCE AND ODOR: SPECIFIC GRAVITY: BOILING POINT (C): MELTING POINT (C): SOLUBILITY IN WATER: PERCENT VOLATILE BY VOLUME: EVAPORATION RATE: VAPOR PRESSURE (mm Hg): VAPOR DENSITY (Air = 1): Solid with no odor 1.05 - 1.26 (H₂O = 1) N/A $380^{\circ}F - 450^{\circ}F$, will degrade above $300^{\circ}F$ (150°C) Insoluble N/A N/A N/A N/A

SECTION X: TRANSPORT INFORMATION

DOT CLASSIFICATION: Non Hazardous

SECTION XI: WASTE XI DISPOSAL METHOD

Disposal must be done in accordance with local, state and federal regulations.

SECTION XII: PREPARATION

The information contained herein is given in good faith, but no warranty, expressed or implied, is made.

DATE ISSUED: April 14, 2003 REVIEWED (no changes): February 2014 PREPARED BY: SpillTech, Telephone Number: 1-800-228-3877.